

# WOW!

## World of Weller®





## WAD 101IG

Order-no.	Model	Description
T005 32 666 71	WAD 101IG	Power unit, 1 channel 150 W for soldering with inert gas

### Perfect solution for lead free soldering applications under an atmosphere of inert gas

With the WSP 80 inert gas safety rest set the WSP 80 soldering iron can be switched to an inert gas soldering iron. The safety rest WDH 10P can be used with the WSP 80IG and WP 120IG. Inert gas is fed through openings in the heating element to envelop the solder joint.

### Accessory



Order-no.	Model	Description
T005 29 197 99	WP 80IG	Soldering iron 80 W for soldering with inert gas 50 °C - 450 °C



Order-no.	Model	Description
T005 29 198 99	WP 120IG	Soldering iron 80 W for soldering with inert gas 50 °C - 450 °C



Order-no.	Model	Description
T005 15 161 99	WDH 10T	Safety rest with Stop & Go function with dry cleaner

Order-no.	Model	Description
T005 87 637 32		Barrel WP120IG

## WDH 10P Set

- Safety rest WDH 10P with inert gas barrel set for soldering iron WSP 80
- 80 W, 24 V
- Lead free soldering



LT Soldering tip series  
page 165-168



Order-no.	Model	Description
T005 15 147 99	WDH 10P Set	Inert gas safety rest set 80 W, 24 V

Scope of supply:

WDH 10P	Safety rest for use with inert gas, ball valve, compressed air hose, 4 mm Inert gas barrel for WSP 80
---------	--

# Weller Safety Rests – Overview

Tools	AK 51	AKT 30	KH 4	KH 6	KH 18	KH 20	KH 20 + FE 75 funnel	KH 20 + FE 80 funnel	KH 25P	KH 27	KHE/KHP	KHE 81 / KHP 81
<b>Fast response</b>												
WP 65												■
WP 120												■
WP 200												
WXP 65												■
WXP 120												■
WXP 200												
<b>Silver Line</b>												
FE 75							■				■	
FE 80								■			■	
MPR 80									■			
WP 80												■
WSP 80					■							■
WSP 150												
<b>Active Tip</b>												
WMRP												
WMRT												
WXMP												
WXMT												
<b>Standard Line</b>												
LR 21											■	
WTA 50	■											
<b>Magnastat controlled low voltage soldering irons</b>												
TCPS						■						
W 61			■									
W 101				■		■						
<b>Desoldering irons</b>												
DSX 80												
DXV 80												
WXDP 120												
DSX 120												
<b>Hot air irons</b>												
HAP 1										■		
HAP 200												
HAP 3000		■										
<b>Inert gas soldering irons</b>												
WP 80IG/120IG												
<b>Solder feeder system</b>												
WSFP 5/8												

Standard safety rest
  Safety rest with Stop & Go function
  Alternative safety rest

