

# Weller Safety Rests – Overview

Tools	AK 51	AKT 30	KH 4	KH 6	KH 18	KH 20	KH 20 + FE 75 funnel	KH 20 + FE 80 funnel	KH 25P	KH 27	KHE/KHP	KHE 81 / KHP 81
<b>Fast response</b>												
WP 65												■
WP 120												■
WP 200												
WXP 65												■
WXP 120												■
WXP 200												
<b>Silver Line</b>												
FE 75							■				■	
FE 80								■			■	
MPR 80									■			
WP 80												■
WSP 80					■							■
WSP 150												
<b>Active Tip</b>												
WMRP												
WMRT												
WXMP												
WXMT												
<b>Standard Line</b>												
LR 21											■	
WTA 50	■											
<b>Magnastat controlled low voltage soldering irons</b>												
TCPS						■						
W 61			■									
W 101				■		■						
<b>Desoldering irons</b>												
DSX 80												
DXV 80												
WXDP 120												
DSX 120												
<b>Hot air irons</b>												
HAP 1										■		
HAP 200												
HAP 3000		■										
<b>Inert gas soldering irons</b>												
WP 80IG/120IG												
<b>Solder feeder system</b>												
WSFP 5/8												

Standard safety rest
  Safety rest with Stop & Go function
  Alternative safety rest



WDH 10	WDH 10T	WDH 10P	WDH 20	WDH20T	WDH 30	WDH 30T	WDH 31	WDH 40	WDH 50	WDH 51	WDH 60	WDH 70	WPH 80	WMRTH
■	■													
■	■													
■								■						
■								■						
						■	■							
						■	■							
■	■													
■													■	
						■	■							
								■	■					
											■			
						■	■							
						■	■							
								■						
						■						■		