



## CT6 Soldering tips

### Chisel shape



Model	°C	A	B	PU	Order No.
<b>CT6 C7</b>	370	3.2		1	4CT6C7- 1
<b>CT6 C8</b>	425	3.2		1	4CT6C8- 1
<b>CT6 D7</b>	370	5.0		1	4CT6D7- 1
<b>CT6 D8</b>	425	5.0		1	4CT6D8- 1
<b>CT6D9</b>	425	5.0		1	CT6D9- 1
<b>CT6 E7</b>	370	7.0		1	4CT6E7- 1
<b>CT6 E8</b>	425	7.0		1	4CT6E8- 1

A = Width mm  
B = Thickness mm  
C = Length mm

Model	°C	A	B	PU	Order No.
<b>CT6 DX8</b>	425	5.0		1	T005 42 318 99N
<b>CT6 F7</b>	425	5.0		1	4CT6F7- 1
<b>CT6 F8</b>	425	5.0		1	4CT6F8- 1
<b>CT6-7 Adapter LHT</b>				1	T005 61 046 67N
<b>CT6-9 Adapter LHT</b>				1	T005 61 046 69N