

# Weller®

## **Fume Extraction Solutions**

We care for your working environment.






## Content

Why Fume Extraction?	3
Zero-Smog <sup>®</sup> System	3
Tip Extraction and Volume Extraction	4
Filter Technology	5
Filter Process	5
Volume Extraction	6 – 17
WFE 85	8
WFE 4S	9
WFE 2X	10
WFE 2S	11
WFE 2ES / WFE 2CS	
WFE 2ES / WFE 2CS	12
Installation Options	

Tip Extraction	18 – 26
WFE	
WFE P	20
WFE 20D	21
FE (Fume Extraction) Soldering Irons	22 – 23
Safety Rests	23 – 24
Accessories	
Spare Part Filter	25
Installation Options	

Pipe Systems for Tip and Volume Extraction

27



Weller

## Why Fume Extraction?

Many work environments today, including soldering, adhesives, welding and laser applications, create particles and gases that can be harmful to the work place and the environment. Most people thought that the move to leadfree soldering would be more nature friendly. In reality lead-free soldering smoke emissions contain more breathable fine dust particles. More and smaller particles are produced due to the higher working temperatures required and because more flux is used in the soldering process.

In many countries legal regulations governing clean air in the work place require that hazardous substances are removed from the air in order to avoid harmful effects on people and machines. It is important to use the correct safety equipment to remove these hazardous substances. Fine particles are more dangerous to inhale than big particles as they get caught more easily and block the alveoli in the lungs.

To protect the operator it is important to use an extraction system that is able to separate these particles and gases and then re-circulates the cleaned air back into the work place. This saves energy and reduces energy costs.

## **Zero-Smog® System**

The Zero-Smog<sup>®</sup> Systems from Weller<sup>®</sup> protect operator and the environment. Their filter systems catch the polluted air right at the source, and prevent the diffusion of particles and gases.

The **Zero-Smog® Systems** have a broad range of filters that can be combined to provide the best solution to the problem. The standard filters are designed for the needs of lead-free soldering, adhesives and laser applications but Weller® has filters suitable for all the most common applications found in industry and laboratories. The Zero-Smog<sup>®</sup> Systems help to create a **good work environment**. They are small and easy to place and have **low noise level** emissions. Extraction arms and nozzles are adjustable so they can get close to the source and guarantee optimum fume capture.

To increase filter lifetime and save energy, most Zero-Smog<sup>®</sup> Systems are fitted with an automatic speed control (dependent on the number of workplaces connected). Effective pre-filters, integrated into the units, save the main filter and can be exchanged very simply.

## Zero-Smog<sup>®</sup> System



# Weller<sup>®</sup> Zero-Smog<sup>®</sup> Systems offer two solutions for fume extraction:

## **Tip Extraction**



## **Volume Extraction**





## **Tip Extraction**

Weller<sup>®</sup> FE (Fume Extraction) soldering irons have a smoke tube integrated into the handle. When soldering the tube is positioned directly above the joint and collects any fumes produced. Fume extraction attachments can be retro fitted to non fume extraction Weller<sup>®</sup> soldering irons.

- Less investment per work place
- Collect pollution direct at sourceUp to 20 collection points
- with one system (200 m apart)
- Ergonomic friendly with easy access to work piece
- No noise
- Minimal air movement

### Volume Extraction

More suitable for applications involving, for example, solder baths, hot air soldering, micro solders and gluing work. Weller<sup>®</sup> offers various mobile systems that purify the air at up to a maximum of 8 workplaces.

- Larger areas can be covered
- Low maintenance
- Mobile
- Quick & easy installation
- Economic for 1 to 8 work places
- Remote control



## **Filter Technology**


Weller<sup>®</sup> **Zero-Smog<sup>®</sup> Systems** are specifically designed for continuous operation in industrial environments. Care and attention at the design stage plus careful component choice and a high quality manufacturing process have given Weller<sup>®</sup> extraction systems a world wide reputation for reliability and longevity.


Weller<sup>®</sup> Zero-Smog<sup>®</sup> Systems have a **three stage filter system** for removing small particles, fumes and gases that are produced in different working processes:

- 1. The hazardous substances are efficiently captured by the nozzle and are absorbed into the filter.
- 2. Bigger particles get caught in the prefilter and smaller particles get caught in the HEPA (High Efficiency Particulate Air) filter.
- 3. The Wide Band Gas Filter removes fumes and adhesives.

End product – clean air – is re-circulated into the workplace.

Filter Class	<b>Recommended Application</b>
F5	for standard applications
F7	for applications with high flux content
H12 / H13	filter for clean rooms 1000 – 100






Filter Class F5, F7: Fine dust filter as per EN 779

Filter Class H12/H13: According EN 1822 HEPA (High Efficiency Particulate Air) Filter

## **Filter Process**



WFE 20D, WFE 2S, WFE 4S, WFE 8S, WFE 2ES, WFE 2CS

#### 1. Fine dust filter

For standard applications with a small amount of flux and pollution gases with high solid content, Weller® offers filter classes **F5 or F7**.

#### 2. Compact filter consisting of: HEPA filter

Filters particles up to  $0,3 \mu$ m. Weller offers HEPA (High Efficiency Particulate Air) filters of class **H12** and **H13**, medium filtration efficiency 99,5 % / 99,95 %.

#### Wide band gas filter

For cleaning harmful fumes and vapours. The Weller wide band gas filter consists of **50 % active carbon** and **50 % Puratex**. Harmful gases with a high molecular weight are cleaned by the active carbon. Puratex is suitable for absorbing gases of lower molecular weight. Because of its composition, Puratex is able to convert a large number of chemical pollutants by means of molecular modification into non-polluting gases.

#### 3. Gas filter (option)

The gas filter is used for extracting adhesive fumes and solvents. Experience has shown that filtering suspended particles is not so vital in this respect. The gas filter is filled with **50 % active carbon** and **50 % Puratex**. The HEPA H12 and H13 is omitted.

filter drawings not true to original

## Zero-Smog<sup>®</sup> Volume Extraction

## **Volume Extraction**

Volume extraction is the **best choice** where extraction over a wide area is required. It is an **economical** way to eliminate polluted process air as there is no need for fixed installations and maintenance requirements are minimal. Arms and nozzles do not require daily cleaning. Energy costs are saved because the cleaned air is re-circulated back into the work area and does not need to be heated or cooled like external air. Weller<sup>®</sup> has a broad range of filter units for volume extraction applications. Speed control allows optimal air flow regulation for each working place independent of the connected workplaces. Units can be remotely controlled via a remote control system (available as accessory) or by a PC (RS232) connection.

AND MARKA PARAMITAN





WFE 8S

WFE 4S

up to 8 workplaces

up to 8 workplaces, small

solder ovens, selective and

reflow soldering equipment

## **Volume Extraction Units**







• WFE 2S up to 4 workplaces

WFE 2X

up to 2 workplaces

## Characteristics

- For applications where extraction over a wide working area is required
- Mobile units suitable for stand alone and central applications
- All units equipped with maintenance free brushless turbine
- Connectable to external air outlet
- Low vacuum up to 2.800 Pa and high volume for efficient volume extraction
- Maximum bridging distance 30 m (WFE 4S using Weller<sup>®</sup> pipe system 75) equally distributed to all connected exhausts
- Cost saving through automatic air flow control which provides each workplace with intelligent air flow regulation regardless of the connected workplaces
- Filter condition monitoring on the unit or by remote control (accessory)
- Wide range of extraction arms and nozzles available to achieve optimal work place configuration

### Areas of application

- Hot air soldering
- Soldering machines, robots, solder baths
- Laser processing
- Adhesive fumes
- Clean room applications (on request)
- Microscope workplaces
- Other fume emitting processes





WFE 2ES / WFE 2CS

up to 2 workplaces

7

## $\mathbf{Zero}\operatorname{-}\mathbf{Smog}^{\circ}$

## **Volume Extraction**

### WFE 8S Powerful fume extraction unit with large integrated pre-filter



### Attributes

 Mobile fume extraction unit purifies air up to 8 workplaces

- Large built-in pre-filter
- The adjustable pressure control guarantees the optimal air flow regulation for each working place - independent of the connected workplaces
- Electronic filter control and easy filter exchange
- 4 wheels to allow easy movement of the unit
- Remote control with alarm function
- Noise damped metal housing
- Quick and simple installation




The fume extraction unit WFE 8S can be connected to up to 8 extraction arms. This makes the unit suitable to use as a small central system in applications such as soldering, adhesives, clean-room work and laser work. It is also capable for connection to small, selective reflow and soldering ovens. The large integrated pre-filter makes the WFE 8S very suitable for lead-free soldering as it is able to catch a large quantity of particles. The WFE 8S is a mobile system that is simple to install – it does not require any permanent installation. Its high quality components keep service needs to a minimum. The combination of low running costs and a flexible system independent of fixed installations produces a unit with a very low cost of ownership. WFE 8S can be connected so that it exhausts air. This is an advantage in applications where re-circulation is not allowed. To further increase the filter lifetime and save energy, the WFE 8S has an automatic airflow control - depending on the number of connected workplaces.

Technical Data	
Maximum capacity	8 workplaces, small and
	medium sized reflow, wafer,
	selective equipment
Maximum extraction rate	615 m³/h
Sound level	< 55 db (A) at 1 m distance
Operating voltage	230/120 V / 50/60 Hz
Power input	450 VA
Maximum vacuum	2.800 Pa
Dimensions (L x W x H)	402 x 796 x 1016 mm
	15.9 x 31.3 x 40 in
Weight	68 kg / 150 lb

#### Scope of supply WFE 8S

- WFE 8S Fume extraction unit 230/120 V / 50/60 Hz with build-in pre-filter
- Compact filter
- Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)

Order No. 230V	005 36 586 99
Order No. 120V	WFE8S
0140111011201	





## Weller

## WFE 4S

Mobile fume extraction unit purifies air up to 8 soldering workplaces



### Attributes

- Mobile fume extraction unit purifies air up to 8 workplaces
- The adjustable pressure control guarantees optimal air flow regulation for each working place independent of the connected workplaces
- Electronic filter control and easy filter exchange
- 4 wheels to allow easy movement of the unit
- Remote control with alarm function
- Noise damped metal housing
- Quick and simple installation



The fume extraction system WFE 4S is userfriendly with quick and simple installation and filter exchange. It has a low noise emission level and is small and convenient to locate within the work area.

The high quality components used in the WFE 4S result in low servicing requirements and long system life. To increase filter lifetime and save on energy, the WFE 4S is fitted with an automatic airflow speed control - depending on the number of connected workplaces. To extend the capacity an external pre-filter can be fixed directly to the WFE 4S.

Technical Data	
Maximum capacity	8 workplaces
Maximum extraction rate	615 m³/h
Sound level	51 db (A) at 1 m distance
Standard connection	pipe system 75
Operating voltage	230/120 V / 50/60 Hz
Power input	450 VA
Maximum vacuum	2.800 Pa
Dimensions (L x W x H)	450 x 450 x 650 mm
	17.7 x 17.7 x 25.6 in
Weight	21 kg / 46.3 lb

# The powerful maintenance free variable speed turbine is electronically controlled and has a maximum capacity of 615 m<sup>3</sup>/h. It has 3 operating modes:

- 1. Standard speed control selected by the user irrespective of the load on the system.
- Speed limiting control the pump speed is automatically varied to match the load on the system.
- Economy control the rate of fume absorption is maintained at a constant value. The operating hours and the filter condition are recorded for maintenance purposes.

## Pre-filter to extend capacity of WFE 2S, WFE 4S, WFE 2X




The pre-filter is recommended for use with solder bath, automatic soldering, laser or other major dust emitting applications. It acts as a first stage in the filter process increasing the lifetime of the main filter units. The prefilter can be fixed directly to the top of the WFE 4S or in conjunction with the WFE 2S and WFE 2X as an external part of the fume extraction system.

#### Scope of supply

- Filter box
  - 2 x hose connections 75
- Filters must be ordered separately (see page 17)

Order No.

005 87 358 62



#### Scope of supply

- WFE 4S Fume extraction unit 230/120 V / 50/60 Hz
   Compact filter
- Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)
- Fine dust pre-filter F7

005 36 256 99
WFE4S

#### Option: WFE 4S with gas filter

- Compact filter for adhesive fumes, consists of: Wide band gas filter (50 % active carbon, 50 % Puratex)
- Fine dust filter F7

005 36 496 99
WFE4SG

## $Zero-Smog^{\circ}$

## **Volume Extraction**

## WFE 2X

Mobile fume extraction unit purifies air up to two workplaces



### Attributes

 Mobile fume extraction unit purifies air at up to 2 workplaces


- Electronic filter control and easy filter exchange
- Wireless remote control with alarm function
- Extra noise damped metal housing
- Quick and simple installation
- Trolley available as accessory
- Minimized foot print
- Switching power supply fits for all global voltages
- Optimized lifetime filter



The WFE 2X is a fume extraction unit and is suitable for applications with a high demand for gas and particle filtration, e.g. soldering, adhesives, clean room work and laser.

It can be placed on a trolley and be moved easily between different work places. Variable speed and the alarm function for filter exchange can be set via the remote control. For applications which produce a large quantity of particles, e.g. lead-free soldering, an external pre-filter can be fitted to increase the lifetime of the main filter. To make installation easier, the WFE 2X can be suspended under the work table with special fittings. An RS 232 interface makes it possible to integrate the software with other process equipment.

Technical Data	
Maximum capacity	2 work places
Maximum extraction rate	140 m³/h
Sound level	< 52 db (A) at 1 m distance
Operating voltage	100 – 240 V / 50/60 Hz
Power input	100 W
Maximum vacuum	2.300 Pa
Dimensions (L x W x H)	210 x 460 x 660 mm
	8.3 x 18.1 x 26 in
Weight	15 kg / 33 lb



WFE 2X Fume extraction unit 100-240 V / 50/60 Hz

consists of: HEPA filter H13, wide band gas filter

(50 % active carbon / 50 % Puratex)

Accessories for WFE 2X see on page 16.

Order No. 230V plug

Order No. 120V plug

Scope of supply

Compact filter

HEPA filter H13 and wide band gas filter

005 36 588 99

WFE2X

### \_\_\_\_\_

WFE 2X Kit 1S



Mobile fume extraction kit

#### Scope of supply

- 005 36 588 99 WFE 2X Fume extraction unit 100-240 V / 50/60 Hz
- 005 36 579 99 KIT 1 WF 60 Sloped stativ extraction arm for
- volume extraction
- consists of:
- 005 36 598 99 Stativ extraction arm

005 36 573 99 Sloped nozzle

- 005 365 75 99 Bench mounting clamps, 2 x
- 005 36 576 99 Extraction hose, 3 m
- 005 36 578 99 Extraction arm

Order No. 230V	005 36 587 99
Order No. 120V	WFE2XKIT1S



# Veller

## **WFE 2S** Mobile fume extraction unit available in two kits



### Attributes

- Mobile fume extraction unit purifies air at up to 4 workplaces
- Electronic filter control and easy filter exchange
- 4 wheels to allow easy movement of the unit
- Remote control with alarm function
- Noise damped metal housing
- Quick and simple installation
- Two kits available

WFE 2 Kit 1



Portable fume extraction kit for one work station

#### Scope of supply

- 005 36 266 99 WFE 2S Fume extraction unit 120/230 V / 50/60 Hz
- 005 36 572 99 KIT 1 WF Sloped 60 for volume extraction consists of: 005 36 578 99 Extraction arm 005 36 577 99 Sloped nozzle 005 36 574 99 Stop valve 005 36 575 99 Bench mounting clamps, 2 x 005 36 576 99 Extraction hose, 3 m

Order No. 230V	005 36 436 89
Order No. 120V	WFE2SKIT1

#### WFE 2 Kit 2



Portable fume extraction kit for two work stations

#### Scope of supply


- 005 36 266 99 WFE 2S Fume extraction unit 120/230 V / 50/60 Hz
- 2 x 005 36 572 99 KIT 1 WF Sloped 60 for volume extraction
- consists of:
- 2 x 005 36 578 99 Extraction arm 2 x 005 36 577 99 Sloped nozzle
- 2 x 005 36 574 99 Stop valve
- 2 x 005 36 575 99 Bench mounting clamps, 2 x
- 2 x 005 36 576 99 Extraction hose, 3 m

Order No. 230V	005 36 456 89
Order No. 120V	WFE2SKIT2

ESD safe low sound level

The fume extraction unit WFE 2S is easy to install and operate. It is designed as a smaller, central system and is supplied complete with flexible hose, arm and bracket, ready for installation at the workplace. A powerful, maintenance-free pump provides continuous fume extraction at a maximum air extraction rate of 230 m<sup>3</sup>/h. A built-in microprocessor controls the adjustable pump speed avoiding unnecessary waste of suction power and saving energy. To optimize the degree of pollutant separation, the WFE 2S can be modified with filters for different applications.

Technical Data	
Maximum capacity	4 work places
Maximum extraction rate	230 m³/h
Sound level	48 db (A) in 1 m distance
Standard connection	pipe system 50
Operating voltage	120/230 V / 50/60 Hz
Power input	275 VA
Maximum vacuum	2.700 Pa
Dimensions (L x W x H)	320 x 320 x 395 mm
	12.6 x 12.6 x 15.5 in
Weight	19 kg / 41.8 lb



#### Scope of supply WFE 2S

- WFE 2S Fume extraction unit 120/230 V / 50/60 Hz
- Compact filter
- consists of: HEPA filter H13, wide band gas filter (50 % active carbon / 50 % Puratex) Fine dust pre-filter F7

Order No. 230V	005 36 266 99
Order No. 120V	WFE2S

#### Option: WFE 2S with gas filter

Compact filter for adhesive fumes. Consists of: Wide band gas filter (50 % active carbon / 50 % Puratex)

Order No. 230V	005 36 466 99
Order No. 120V	WFE2SG

## **Volume Extraction**

## WFE 2ES / WFE 2CS Fume extraction unit as economical solution



Portable fume extraction kit for one work station

The fume extraction unit WFE 2ES is easy to install and operate. It is designed as a smaller central system and is supplied complete with flexible hose, arm and bracket, ready for installation at the workplace.



Technical Data	
Maximum capacity	2 work places
Maximum extraction rate	220 m³/h
Sound level	55 db (A) at 1 m distance
Operating voltage	230V / 50Hz (115V / 60Hz)
Power input	115 VA
Maximum vacuum	1.800 Pa
Dimensions (L x W x H)	320 x 320 x 395 mm
	12.6 x 12.6 x 15.5 in
Weight	9 kg / 19.8 lb

#### Scope of supply

- 005 36 506 99 WFE 2ES Fume extraction unit consists of:
- HEPA filter H12, active carbonate foam Fine dust pre-filter F5
- 005 36 571 99 KIT 1 WF Funnel 60
- consists of:
- 005 36 578 99
   Extraction arm

   005 36 573 99
   Funnel nozzle

   005 36 574 99
   Stop valve

   005 36 575 99
   Bench mounting clamps, 2 x

   005 36 576 99
   Extraction hose, 3 m

Order No. 230V	005 36 516 89
Order No. 120V	WFE2ES KIT1

#### **Option: Arm with sloped nozzle**

005 36 572 99 KIT 1 WF Sloped 60 for volume extraction consists of:
 005 36 578 99 Extraction arm
 005 36 577 99 Sloped nozzle
 005 36 574 99 Stop valve
 005 36 575 99 Bench mounting clamps, 2 x
 005 36 576 99 Extraction hose, 3 m

#### **Option: WFE 2CS with speed control**

Order No. 230V	005 36 526 99
Order No. 120V	WFE2CS


### Attributes

 Mobile fume extraction unit purifies air up to 2 workplaces

and the second secon

- Easy filter exchange
- Quick and simple installation
- Optional: Speed control (WFE 2CS)










## **Installation Options**


## Installation option for a central system with WFE 2S

Total pipe length 15 m (590.55 in)



## Installation option for a central and stand alone system with WFE 4S

Total pipe length 30 m (1181.10 in)



## **Volume Extraction**

## Accessories

When soldering, gluing or working with solvents it is important to place the nozzle as close to the source as possible to prevent harmful particles and gases being spread into work area. The Weller<sup>®</sup> 60 mm (2.36 in) flexible extraction arms allow the quiet and efficient capture of polluted air. The arms and nozzles are simple to install due to the click-on funnels and can easily be fixed into the required position.

a stand and the stand and the stand









Order No.	Description
005 87 358 47	<b>Hose connection 50</b> for WFE 2S and WFE 4S, e.g. for the direct connection of accessories by means of 50 mm (1.96 in) extraction hose. Plastic, black.
005 87 358 32	<b>Hose connection 75</b> for WFE 2S and WFE 4S, e.g. for connection to a stand alone system by means 75 mm (2.95 in) pipe or 75 mm (2.95 in) extraction hose. Plastic, black.
005 87 358 48	<b>Hose connection 50, 90°</b> for WFE 2S and WFE 4S, e.g. for the direct connection of accessories by means of 50 mm (1.96 in) extraction hose. Plastic, black.
005 87 358 33	<b>Hose connection 75, 90°</b> for WFE 2S and WFE 4S, e.g. for connection to a stand alone system by means of 75 mm (2.95 in) pipe or 75 mm (2.95 in) extraction hose. Plastic, black.
005 87 353 13	<b>Extraction hose 75,</b> ø 75 mm (2.95 in), for connection to pipe system 75. Sold by metre. Plastic, grey/black, flexible.
005 87 354 27	<b>Extraction hose 60,</b> 1 m (39,37 in), ø 60 mm (2.36 in), for connection to pipe system 50. Sold by metre. Plastic, grey/black, flexible.
005 36 576 99	<b>Extraction hose 60,</b> 3 m (118,11 in), ø 60 mm (2.36 in), for connection to pipe system 50. Plastic, grey/black, flexible.
005 87 627 56	<b>Extraction hose 60,</b> 5 m (196,85 in), ø 60 mm (2.36 in), for connection to pipe system 50. Plastic, grey/black, flexible.
005 87 627 55	Hose adapter to extend 60 mm hoses
005 87 358 79	Hose clamp 50 – 70 mm, (1.96 - 2.75 in), 2 units, for securing extraction hose 50.
005 87 358 31	Hose clamp 70 – 90 mm, (2.75 - 3.54 in), 2 units, for securing extraction hose 75.



# Weller®












Order No.	Description
005 36 598 99	<b>Articulated extraction arm,</b> 60 mm diameter, flexible extraction arm with articulated joint and and bench clamp. ESD safe.
005 36 578 99	<b>Flexible extraction arm,</b> 60 mm (2.36 in) diameter, for sloped and funnel nozzles. Maximum length 1 m (39.37 in), ESD safe.
005 36 577 99	<b>WF 60</b> sloped nozzle for flexible and stativ extraction arm.
005 36 573 99	WF funnel nozzle 60, for flexible and stativ extraction arm, 230 mm x 100 mm.



005 87 358 45

**Exhaust hood,** 200 x 100 mm (7.87 x 3.93 in), recommended for use with hot air soldering operations uses extraction hose 60.

## **Volume Extraction**

## Accessories

	Order No.	Description
and a second	005 36 574 99	<b>WFV 60 Stop valve.</b> Table connector for 60 mm (2.36 in) flex arm and extraction tube including air flow valve.
JJ	005 36 575 99	<b>Bench mounting clamps, 2 x.</b> Maximum width of clamp 100 mm (3.93 in). 100 mm (3.93 in) diameter. Metal.
0	005 87 627 53	<b>50/60 Adapter with Silicone O-ring,</b> to connect 60 mm hoses to WFE 2ES, WFE 2CS and WFE 2S.
	005 87 627 50	<b>40/60 Adapter</b> for applications using the 60 mm (2.36 in) extraction system connected to the <b>former</b> WFTB 50 and WFFMP 50.

and the second second

**Accessories for WFE 2X** 



Order No.	Description
005 36 591 99	<b>Hanging device</b> for table mounting for fume extraction unit WFE 2X.
005 36 592 99	<b>Trolley</b> for fume extraction unit WFE 2X.



## Exhaust accessories to blow waste air out of a building

Order No.	Description
005 87 359 20	<b>Exhaust adapter</b> of pipe 100 to fume extraction unit WFE 20D.
005 87 358 40	<b>Exhaust adapter</b> of pipe 100 to fume extraction unit WFE 4S.
005 87 359 15	Exhaust adapter of pipe 75 for fume extraction unit WFE 2S.

Remote control for tip and volume extraction units



Order No.	Description
005 87 359 09	<b>Remote control</b> for fume extraction units WFE 20D, WFE 2S, WFE 4S and WFE 8S. Switching unit on/off, speed setting (only WFE 2S / WFE 4S), filter status display.
005 31 191 99	Interface cable RS 232, 2 m (78.74 in) for remote monitoring by PC (type 1:1).
005 36 593 99	<b>Remote control</b> for fume extraction unit WFE 2X with 2 m (78.74 in) cable.

## **Replacement Filters**

Order No.	Spare filter for WFE 8S:	Order No.	Spare filter for WFE 2X:	Order No.	Spare filter for WFE 4S:
005 36 594 99 005 36 595 99	Replacement pre-filter Replacement compact filter (4 pieces in one pack) Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)	005 36 590 99	Replacement compact filter Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)	005 87 358 37 005 87 358 36 005 87 358 38	Fine dust filter F5 (10 pieces) Fine dust filter F7 (10 pieces) Compact filter Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)
				005 87 358 35	Option: Adhesive fume filter (50 % active carbon, 50 % Puratex)


Order No. 005 87 358 84	Spare filter for WFE 2S: Fine dust filter F5 (10 pieces)	Order No. 005 87 627 01	Spare filter for WFE 2ES: Fine dust filter F5 (10 pieces)	Order No.	Spare filter for pre-filterbox:
005 87 358 85 005 87 358 83	Fine dust filter F7 (10 pieces) Compact filter		Compact filter Consists of: HEPA filter H12,	005 87 358 60	Pocket filter F7 for large quantities of dust
	Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)		wide band gas filter (10 % active carbonate foam)	005 87 359 24	Filter bag for sticky residuce (e.g. large quantities of liquid flux)
005 87 358 95	Option: Adhesive fume filter (50 % active carbon, 50 % Puratex)				

## **Tip Extraction**



## **Tip Extraction**

Weller<sup>®</sup> FE (Fume Extraction) soldering irons have a smoke tube adapted to the handle. When soldering the tube is positioned directly above the joint and collects any fumes produced. Fume extraction irons can be connected to the Weller<sup>®</sup> Zero-Smog<sup>®</sup> Systems WFE, WFE P (both bench mounted units driving up to 2 irons) or WFE 20D – a mobile unit driving up to 40 irons. A safety rest with Stop + Go function switches the extraction system on when the FE soldering iron is removed from the safety rest and off after a short delay when the iron is replaced (WFE & WFE P only). Fume extraction attachments can be retro-fitted to non fume extraction Weller<sup>®</sup> soldering irons.





## **Tip Extraction Units**

### **Characteristics**

- FE (Fume Extraction) soldering irons extract fumes directly at the soldering tip.
- Less airflow and high vacuum, up to 12.000 Pa for efficient fume extraction.
- Maximum bridging distance 200 m (7874 in), WFE 20D requires Weller<sup>®</sup> pipe system 50.
- Filter condition warning LED on the unit or remote control via RS 232 and PC (WFE 20D).
- Variable electronically controlled pump speed, adjustable at the unit or by remote control via RS 232 and PC (WFE 20D).

### **Areas of application**

- Hand soldering
- Small solder baths



WFE 20D

up to 40 workplaces



### WFE P

up to 2 workplaces



WFE

up to 2 workplaces

# **Tip Extraction**

## WFE

Small, portable, compressed air driven fume extraction unit



	<i>6</i>
ESD safe	low sound leve

Technical Data	
Maximum capacity	2 FE soldering irons
Sound level	< 39 db (A) at 1 m distance
Maximum vacuum	20.000 Pa
Operating pressure	3,5 - 6 bar
Air consumption	30 l/min
Height	200 mm (7.8 in)
Diameter	140 mm (5.5 in)
Weight	2,7 kg / 5.9 lb

The fume extraction unit WFE requires clean and oil-free compressed air. The vacuum is generated by a maintenance-free compressed air converter. The contaminated air is purified by a pre-filter and main filter system. A compressed air cleaning filter removes additional odours caused by the compressed air. This highly efficient filter system makes the WFE a genuine air recovery system. The filter-lift system allows fast and convenient filter cartridge replacement. The FE (Fume Extraction) soldering irons are connected directly to the unit – additional leads are not required.


#### Scope of supply

- WFE Fume extraction unit
- Compressed air cleaning filter
- Compact filter
- Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)
- Fine dust filter F7

#### Order No. 005 36 402 99

### Attributes

- Up to 2 FE soldering irons can be connected
- Maintenance-free compressed air converter
- Portable unit for stand alone applications



### WFE P Small, portable, electrically driven fume extraction unit





#### **Technical Data** Maximum capacity 2 FE soldering irons Sound level < 45 db (A) at 1 m distance Operating voltage 230 V / 50 Hz Power input 70 W Maximum vacuum 30.000 Pa Height 295 mm (11.6 in) Diameter 140 mm (5.5 in) 4 kg / 8.8 lb Weight

#### The Weller® WFE P is a line voltage fume extraction unit designed to run with one or two FE (Fume Extraction) soldering irons. The WFE P has an electric, long-life, soundproofed vacuum pump to produce the required vacuum – it does not need a compressed air supply. The vacuum pump has two power settings which can be selected by means of rocker switches depending on the number of FE soldering irons connected to the unit. This saves energy. The motor is maintenance-free and has a thermal over load to protect the unit. The filter lift system allows fast and convenient main filter replacement. FE soldering irons are connected directly to unit – additional leads are not required.


#### Scope of supply

- WFE P Fume extraction unit
- Compact filter
  - Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)
- Fine dust filter F7

Order No. 230V	005 36 386 99
Order No. 120V	005 36 232 99

#### Attributes

- Up to 2 FE soldering irons can be connected
- Electric vacuum pump to produce the required vacuum
- 2 power stages for higher extraction perfomance with 2 FE soldering irons
- Portable unit for stand alone applications





WFE 20D Mobile, powerful, electronically driven fume extraction unit






Up to 5 Weller® FE (Fume Extraction) soldering irons can be connected directly to the fume extraction unit WFE 20D. Using the Pipe System 50 (available as accessory) up to 40 FE soldering irons can be supported by the unit. The powerful maintenance-free turbine generates a vacuum of 12.000 Pa and is electronically controlled. Operating hours and filter contamination level are also recorded electronically. The filter system achieves a filtration rate of 99,95 % as per EN 1822 with a particle size of 0,12  $\mu$ m.

#### **Characteristics**

- Two operating modes: Mode 0: Vacuum regulated to 12.000 Pa Mode 1: Extraction performance can be set between 20 % – 100 % with the control buttons.
- Electronic filter check (LED) through differential pressure measurement.
   If the specified degree of contamination is exceeded, the unit switches off.
- Electronic filter operation status display. For better management of filter change intervals – the filter operating hours can be pre-specified. The need for filter change is indicated in good time allowing adequate time for filter procurement and replacement. Interface RS 232 for remote monitoring or remote control.
- Remote control available as accessory.

#### Attributes

- Up to 40 FE soldering irons can be connected
- Electric driven, maintenance free turbine produces the required vacuum
- 4 wheels to allow easy movement of the unit
- Mobile unit for central and stand alone applications
- Central installation for pipe systems up to 200 m (7874 in)



Technical Data	
Maximum capacity	40 FE soldering irons
Sound level	< 51 db (A) at 1 m distance
Operating voltage	230 V / 50 Hz 120 V / 60 Hz
Power input	630 VA
Maximum vacuum	12.000 Pa
Max. delivery rate	100 m³/h
Dimension (L x W x H)	450 x 450 x 695 mm
	17.7 x 17.7 x 27.3 in
Weight	45 kg / 99 lb

#### Scope of supply

- WFE 20D Fume extraction unit
- Compact filter
   Consists of: HEPA filter H13, wide band gas filter
   (50 % active carbon, 50 % Puratex)
- Fine dust filter F7

Order No. 230V	005 36 476 99
Order No. 120V	WFE20D

## **Tip Extraction**



## FE (Fume Extraction) Soldering Irons



The smoke absorption tube is integrated into the handle. It can be placed over the joint when soldering but can be retracted when access to the joint is a problem and can also be removed for cleaning. The irons are temperature controlled, ergonomic and allow precise handling. These electronically controlled irons

ESD safe


can be driven from any Weller® power unit compatible with the rating of the iron or any Weller® rework station. The range of iron power ratings and the extensive range of solder tips mean that there is an iron to suit all applications. The FE soldering irons are supplied with a burn proof hose 5 mm (0.19 in) diameter, 2,5 m (98.42 in) long.




Order No.	Description
005 33 150 99	<b>FE 50</b> Soldering iron set 50 W / 24 V, with safety rest KH 20*. Not available in US.
005 32 152 99	<b>FE 50M</b> Soldering iron set 50 W / 24 V, Magnastat controlled with safety rest KH 20*. Not available in US.
005 33 151 99	<b>FE 75</b> Soldering iron set 80 W / 24 V with safety rest KH 20*. For use with LT tips.
005 26 162 99	<b>FE 80</b> Soldering iron 80 W / 24 V with safety rest KH 20*. Not available in US.

\* Cleaning brush for FE tubes and fume extraction funnels are included in the scope of supply of the soldering irons for use with KH 20 and KH 23 safety rests.

## **FE Attachments**





A range of FE attachments are available to fit

For Weller<sup>®</sup> soldering irons WP 120, WP 80, WSP 80, WMP, MLR 21 or soldering irons with handle diameter 10 - 13 mm (0.39 - 0.51 in). Clip will be fixed with an silicone O-ring to the soldering iron.

	0
-	0
	00

Order No.	Description
005 29 186 99	FE Attachment with tube, ø 6 mm (0.23 in) for WP 120, WSP 80, WP 80, MLR 21,
	MLR 80, WMP.
005 29 185 99	FE Attachment with tube, ø 4,5 mm (0.17 in) for WP 120, WMRP and WSP 80,
	WP 80, MLR 21, MLR 80, WMP for fine soldering applications.
005 87 448 75	FE Spare Clip-Set for FE attachment, tube ø 4,5 mm (0.17 in).
005 87 448 76	FE Spare Clip-Set for FE attachment, tube ø 6,0 mm (0.23 in).
005 15 156 99	WDH 50 safety rest for soldering iron with FE attachment.
005 25 125 99	FE Attachment for LR 21, LR 82, TCPS, W 61, W 101, WSP 150 with safety rest AK 1.
005 28 126 99	FE Attachment for WSF 80D5/8.
005 13 125 99	FE Attachment for DS 22, DS 80 and DSX 80 desoldering iron.



## **Accessories for FE Irons**



Order No.	Description
005 36 352 99	<b>Locking clip.</b> The locking clip is used to disconnect FE (Fume Extraction) soldering irons that are not required so that there is no unnecessary loss of extraction power. The clip can be operated quickly and easily.
005 25 410 00	<b>Extraction hose (spare part)</b> Heat-resistant silicone hose, ø 5 mm (0.19 in), for all FE (Fume Extraction) soldering irons (sold by metre).



Order No.	Description
	Cord support. The cord support keeps the soldering iron cord out of
	the direct working area. This allows easier handling of the soldering iron.
005 15 065 99	Cord support for safety rest AK 20.
005 15 066 99	Cord support for safety rest KH 20/23.

## Safety Rests for FE Soldering Irons



Order No.	Description
005 15 030 99	<b>AK 20</b> Safety rest for FE 50, FE 50M, FE 75, FE 80; for LR 21, LR 82 and TCP with attachment.
005 15 020 99	<b>KH 20</b> Safety rest for FE 50, FE 50M, FE 75, FE 80.
005 15 023 99	KH 23 Safety rest for FE 25.
005 15 140 99	<b>WPH 80</b> Safety rest for WSP 80FE; for MLR 21 with FE attachment.

# **Tip Extraction**



## Safety Rests with Stop + Go Function for FE soldering irons together with fume extraction

units WFE and WFE P

The Weller® Stop + Go safety rests are recommended accessories for FE soldering irons using the WFE or WFE P extraction units. A fibre optic sensor switches the extraction unit on when the FE soldering iron is removed from the

0

safety rest and off when the FE soldering iron is replaced in the safety rest. After a short delay to gather the fumes from any solder on the tip, it switches the unit off. This saves the soldering tip and reduces the running costs.

Order No.	Description
005 15 086 99	<b>KHP</b> Pneumatic basic unit (for WFE), safety rest with Stop + Go function with fibre optic sensor for soldering irons FE 25, FE 50, FE 50M, FE 75 and FE 80.
005 15 076 99	<b>KHE</b> Electric basic unit (for WFE P), safety rest with Stop + Go function with fibre optic sensor for soldering irons FE 25, FE 50, FE 50M, FE 75 and FE 80.
005 15 080 99	<b>KHE/P</b> Second safety rest with fibre optic sensor for extending to 2 workplaces for soldering irons FE 25, FE 50, FE 50M, FE 75 and FE 80.
005 15 084 99	<b>KHP 80</b> Basic unit pneumatic (for WFE) safety rest with Stop + Go function with fibre optic sensor for soldering iron WSP 80FE.
005 15 083 99	<b>KHE 80</b> Basic unit electric (for WFE P) safety rest with Stop + Go function with fibre optic sensor for WSP 80FE.
005 15 141 99	<b>KHE 80/P 80</b> Second safety rest with fibre optic sensor for extending to 2 workplaces for WSP 80 FE.
005 15 156 70	WDH 50 E/P Safety rest for soldering iron with FE Attachment

Not available in US.

0



Accessories for workbench installations



## **Spare Part Filters**

Order No.	Description
005 36 316 99	<b>Extraction hose 40</b> , 1 m (39.37 in), ø 40 mm (1.5 in). Complete with 2 connecting elements for direct connection of unit (WFE 20D) to pipe system 50. Plastic, grey/black, flexible.
005 36 414 00	<b>Extraction hose 40</b> , ø 40 mm (1.5 in) without connecting elements. Sold by metre. Plastic, grey / black, flexible.
005 36 415 99	<b>Connecting element 40 – 50</b> for connecting extraction hose 40 and pipe system 50. Rubber, black.
005 36 326 99	<b>Extension hose</b> DN 17 (13 x 3 mm), 5 m (198.85 in), ø 17 mm (0.6 in), used where the fume extraction iron is further than 2,5 m (98.42 in) from the pipe system 50. <b>Note:</b> Connection nipple for hose 17 and adapter 17 will be required. Plastic, transparent.
005 87 358 65	<b>Connection nipple</b> for extension hose 17. Amend direction to read direct.
005 87 358 66	Nut G 3/8" for connection nipple.
005 36 343 99	<b>Adapter 17</b> for connection extension hose DN 17 with ø 5 mm (0.19 in) extension hose of FE irons.
005 36 338 99	<b>Connection nipple</b> for 5 mm (0.19 in) diameter extraction hose to connect FE soldering irons directly to pipe system 50. The connection nipple is screwed at any point into the pipe system.
005 87 350 50	End cap to close off to connection nipple.


Order No.	Spare filter for WFE:	Order No.	Spare filter WFE 20D:	Order No.	Spare filter for WFE P:
005 87 357 57 005 36 410 99	Compressed air - cleaning filter Compact filter Consists of: HEPA filter H13, wide band gas filter (50 %	005 87 358 37 005 87 358 36 005 87 358 38	Fine dust filter F5 Fine dust filter F7 Compact filter Constists of: HEPA filter H13,	005 36 410 99	Compact filter Consists of: HEPA filter H13, wide band gas filter (50 % active carbon, 50 % Puratex)
005 36 407 99	active carbon, 50 % Puratex) Compact filter Consists of: HEPA filter H13, wide band gas filter (100 %		wide band gas filter (50 % active carbon, 50 % Puratex)	005 36 407 99	Compact filter Consists of: HEPA filter H13, wide band gas filter (100 % active carbon)
005 36 421 99 005 36 597 99	active carbon) Fine dust filter F7 (3 pieces) Compact filter with enlarged pre-filter			005 36 421 99 005 36 597 99	Fine dust filter F7 (3 pieces) Compact filter with enlarged pre-filter

## **Tip Extraction**




## **Installation Options**

Installation option for a central system with WFE P



## Installation option for a central and stand alone system with WFE 20D





## **Pipe Systems for Tip and Volume Extraction**

### **Pipe System 50 Tip Extraction**

Tip extraction systems demand a high quality, constant level of vacuum across the installation. To achieve this it is necessary to use a pipe system with a relatively small diameter. The Weller® pipe system 50 allows extraction **installations of up to 200 m (7874 in)** when used with the WFE 20D unit in a stand alone system. The pipe sections are designed to join together and have internal sealing bushes. In a central system, the FE soldering irons are connected directly to the fume extraction units.

### **Pipe System 75 Volume Extraction**

Volume extraction systems require a large volume of air to be extracted and the level of vacuum is of lesser importance. This means that a relatively large diameter pipe system is required. If the pipe diameter is too small the flow resistance is increased and extraction capacity reduced. The pipe system 75 allows **installations up to 30 m (1191.1 in)** with the WFE 4S used in a stand alone system. The pipe sections are designed to join together and have internal sealing bushes.

Order No.		Description
Pipe System 50	Pipe System 70	
005 36 323 99	005 87 358 70	<b>Pipe,</b> 2 m (78.74 in), with seal at one end. PEHD*, black.
005 36 322 99	005 87 358 69	<b>Right angle pipe,</b> 90°, 0,2 m (7.87 in), with seal at one end. PEHD*, black.
005 36 344 99	005 87 358 71	<b>T-piece,</b> 2 x 90°, 0,5 m (19.68 in), with 3 seals. PEHD*, black.
005 36 321 99		<b>Branch,</b> 2 x 45°, 0,3 m (11.81 in), with 2 seals. PEHD*, black.
005 36 319 99		Double socket. PEHD*, black.
005 36 324 99	005 87 358 55	End seal. Plastic, transparent.
005 36 329 99	005 87 358 64	<b>Pipe clamps</b> for pipes, e.g. for securing to wall. Plastic, grey.
	005 87 358 63	Adapter pipe system 75 to pipe system 50 with seals
	005 87 358 56	Adapter PEHD* pipe system 75 to pipe system 50, without seals.

\*PEHD = Polyethylen High Density

### GERMANY

**Cooper Tools GmbH** Carl-Benz-Straße 2 74354 Besigheim Tel: (07143) 580-0 Fax: (07143) 580-108

#### ITALY

**Cooper Italia S.r.l.** Viale Europa 80 20090 Cusago (MI) Tel: (02) 9033101 Fax: (02) 90394231

#### CANADA

Cooper Hand Tools – Canada 164 Innisfil Street Barrie, Ontario Canada L4N 3E7 Tel: (705) 728 5564 Fax: (800) 403 8665

#### USA

Cooper Hand Tools World Headquarters 1000 Lufkin Road Apex, NC 27539 USA Tel: (919) 387 0099 Fax: (919) 387 2614

### S W I T Z E R L A N D **Erem S.A.** Rue de la Roselière 8 1400 Yverdon-les-Bains Tel: (024) 426 12 06 Fax: (024) 425 09 77

C H I N A **Cooper Hand Tools** 18<sup>th</sup> Floor, Yu An Building 738 Dongfang Road Pudong, Shanghai 200122 China Tel: (21) 5111 8300 Fax: (21) 5111 8446

#### FRANCE

Cooper Tools S.A.S. 25 Rue Maurice Chevalier BP 46 77832 Ozoir-la-Ferrière Cedex Tel: (01) 60.18.55.40 Fax: (01) 64.40.33.05

### GREAT BRITAI

Cooper Tools A Division of Cooper (GB) Ltd. 4<sup>th</sup> Floor Pennine House Washington, Tyne & Wear NE37 1LY Tel: (0191) 419 7700 Fax: (0191) 417 9421

## AUSTRALIA

Cooper Tools Pty. Limited P.O. Box 366 519 Nurigong Street Albury, N.S.W. 2640 Australia Tel: (2) 6058-0300 Fax: (2) 6021-7403

www.coopertools.eu www.weller.eu



005 56 171 06 / 04.09 WD 5.0